

Test Report

Number: GZHH0062626804

Applicant: GUANGZHOU SHANGYE JEWELRY CO., LTD.
2ND FLOOR, BUILDING A, SHIQIAO GOLD AND SILVER
PROCESSING ZONE, PANYU DISTRICT, GUANGZHOU
CITY


Date: Dec 19, 2025

Attn: EASON

Sample Description:

Ten (10) pieces of submitted sample said to be :

Item Name	:	Tennis Chain
Item No.	:	C618004-7
Buyer	:	Eason
Manufacturer	:	Guangzhou Shangye Jewelry Co., Ltd.
Country of Destination	:	EU/USA
Country of Origin	:	China
Date Sample Received	:	Dec 05, 2025
Testing Period	:	Dec 05, 2025 to Dec 18, 2025



Tests conducted:

As requested by the applicant, refer to attached page(s) for details.

To be continued



Page 1 of 3

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District,
Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road,
Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、
601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com



Test Report

Number: GZHH0062626804

Conclusion:

Tested Sample

Submitted Samples

Standard/Test Item

Tensile Strength Test on Tennis Chain

- As per the client's requirement

Result


See test

conducted

Authorized by:

For Intertek Testing Services Shenzhen Ltd.

Guangzhou Branch, Hardlines



Victor T.J. Wang
General Manager



Should you have any query on this report, please click the link below:
https://verifyindex.intertek.com.cn/home/index?id=hl_report_verify



Page 2 of 3

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com



Test Report

Number: GZHH0062626804

Tests Conducted

1 Tensile Strength Test on Tennis Chain

As per the client's requirement, the tested samples were subjected to the following test.

Executive Summary:

Test Item	Testing Citation / Method	Requirement / Limit	Result
Tensile Strength Test	The client's requirement	Record the tensile force value at the moment when the chain breaks.	Recorded: Breaking force and location: The chain clasp: 13.78 lbs; The main chain: 17.08 lbs.

End of report

The statements of conformity reported have considered the decision rule agreed, namely that Intertek have taken account of measurement uncertainty as calculated by Intertek, and applied according to ILAC-G8/09:2019 (Non-binary acceptance based on guard band $w = U$) except designation from the customer, regulation or test specification. This decision rule only applies to the numeric test results.

The sample(s) and sample information hereto are provided by the client who shall be solely responsible for the authenticity and integrity thereof. The results shown in this report relate only to the sample(s) tested. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. This report shall not be reproduced unless with prior written approval from Intertek Testing Services Shenzhen Limited, Guangzhou Branch.



Page 3 of 3

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、

601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com

